

S/N 55010007 Registration N629PT



#### **AIRFRAME**

Total Time 582.2 Hours 428 Landings

#### **ENGINES**

Honeywell HTF7500E: Enrolled on MSP Gold

Engine 1: P131202 582.2 Hours 428 Cycles Engine 2: P131203 582.2 Hours 428 Cycles

#### **APU**

Honeywell GTCP-36-150: Enrolled on MSP Gold

Serial Number P-157 792 Hours

#### **MAINTENANCE**

FACTORY SERVICE CENTER MAINTAINED 12 MONTH DUE – APRIL 2021 24/36 MONTH DUE – APRIL 2022 60 MONTH DUE – MAY 2021



S/N 55010007, Registration N629PT

#### **AVIONICS**

- Four Collins 15.1" active matrix LCD screens
- Dual FMS w/ Takeoff and Landing performance calculation capability
- Dual Collins GPS-4000S w/ WAAS/LPV
- Dual Collins NAV-4000
- Dual Collins DME-4000
- Synthetic Vision System (SVS)
- Single ADF
- ADS-B Out

#### ADDITIONAL EQUIPMENT

- Swift Broadband High Speed Data
- DataLink Graphical Weather / XM Weather
- Enhanced Seat (6)

- Triple Collins VHF-4000
- SATCOM
- Collins ALT-4000 Radio Altimeter
- Dual Collins TDR-94D Transponders
- CVR
- FDR
- TCAS II
- Surface Management System
- CPDLC
- E<sup>2</sup>VS HUD
- Autobrake

S/N 55010007 Registration N629PT



# NB23PT

#### **INTERIOR**

Nine (9) Passenger Club configuration with a forward 2-place divan, two (2) aft forward-facing seats, and belted lav.

#### **EXTERIOR**

**Embraer Brand Paint Scheme** 













































