





AIRFRAME

Total Time 7,489 Hours 4,113 Landings

ENGINES

Honeywell TFE731-50R-1H, Enrolled on MSP Gold S/N P122188 6,908 Hours 3,900 Cycles S/N P122189 6,908 Hours 3,900 Cycles

APU

Honeywell GTCP 36-150, Enrolled on MSP APU: 5,989 Hours

MAINTENANCE

No Known Damage History G- Inspection performed July 2022 CZI & MPI performed in 2022

AVIONICS

- Dual Collins DME-400
- Dual Collins ADF-462
- Collins HF-903A HF Radio
- TCAS II w/ change 7.1
- Collins RTA-858 Weather and Radio Receivers
- Dual Collins VHF Communication Transceivers
- DME Distance Measuring Equipment Collins DME-4000

- Additional Power Outlets at divan and VIP seat area
- ALT-4000 Radio Altimeter
- · Satellite Telephone
- Honeywell ADZ-810 Air Data System
- Data Recorder (CAT.IDE.A.190)
- FDR Flight Data Recorder
- ADS-B Out Mode S Transponders

ADDITIONAL EQUIPMENT

- Rotary Ice Detection System
- LED Cockpit Flood Flights
- PBE Portable Breathing Equipment
- Premium Cabin Management System
- Jump Seat
- Life Vests (for 8 seats)
- Smoke Goggles
- 77cu. ft. Oxygen Bottle





INTERIOR

Executive nine passenger interior features a forward four place club setting, aft three place divan opposite a single forward-facing seat, and forward jump seat. Aft lavatory includes lighted vanity and sink.

Carpet replacement in 2022.



EXTERIOR

Overall White, in excellent condition, last painted in 2018 Freshly painted wings in Spring 2023































