





# **AIRFRAME**

Total Time 11,482.1 Hours 6,795 Landings

# **ENGINES**

Honeywell TFE731-5BR-1H, Enrolled on JSSI

s/n P129313: 4,100.8 Hours 2,655 Cycles s/n P107783: 4,745.0 Hours 3,325 Cycles

## **APU**

Honeywell GTCP 36-150W

s/n P-691 5,960 Hours

# **MAINTENANCE**

Engine #1 Installed 1/2023, Engine #2 Installed 2/2024

CAMP Electronic Maintenance Tracking
Avionics Enrolled on CASP



### **AVIONICS**

- Dual Collins ADF-462
- Dual Collins AHS-6000 AHRS, Meggitt Standby
- Collins FGC-3000 ICFS A/P & FD
- Dual Collins VHF-422C w/8.33 Spacing
- Universal CVR-120 Min
- Collins ProLine 21 4-Tube 8x10-Inch EFIS
- Dual Collins FMS-6000 Version 3.0.3
- Dual Collins GPS-4000A

- Collins HF-9000 w/SELCAL
- Dual Collins VIR-432 w/FM Immunity
- Collins ALT-4000 Radar Altimeter
- RMI
- Honeywell Mark V EGPWS
- TCAS 7.1 Installation Underway
- Garmin GTX-3000 Mode S Transponders
- Collins RTA-858 Weather Radar

## ADDITIONAL EQUIPMENT

- Aviation Partners Blended Winglets
- Gogo Avance L3 WiFi
- Dual DB Systems Model 7000 Audio Panels
- 406 MHz ELT w/Nav Interface

- Third Long Range Oxygen Bottle
- Collins ADC-3000 Air Data Computers
- 41,000-Ft Altitude Kit





## **INTERIOR**

#### **New Full Interior, September 2018**

Executive nine passenger interior features a forward four place club setting, aft three place divan opposite single club seat, jumpseat and aft belted lavatory seat. Seating is Sand leather, wool blend carpeting. Additional cabin amenities include forward illuminated galley and bar with beverage storage, Airshow 400 with Airshow Network and cabin briefer, DVD/CD, dual 15-inch monitors, 115v AC outlets, aft lighted sink and mirror. New carpet, 2022.

# **EXTERIOR**

### New July, 2015 by Duncan Aviation

Matterhorn White upper with Royal Blue lower, Royal Blue and Yellow accent striping.









# **2002 Hawker 800XP**

MSN 258585 / N585VC





# **2002 Hawker 800XP**

MSN 258585 / N585VC













