



2002 Hawker 800XP 258588 N799S

2002 Hawker 800XP

258588, N799S



AIRFRAME

Total Time: 7,265 Hours 5,601 Landings

ENGINES

Model: Honeywell TFE731-5BR-1H **Enrolled on MSP**

Engine 1: 7,180 Hours 5,531 Cycles

Engine 2: 7,158 Hours 5,504 Cycles

APU

Model: GTCP36-150 (W) **Enrolled on MSP**

APU: 5,422 Hours

HIGHLIGHTS

No Known Damage History

Professionally owned and operated

2002 Hawker 800XP

258588 , N799S

AVIONICS

- Collins Pro Line 21 Integrated Avionics Suite
- Dual Collins flight guidance system with autopilot
- Dual Collins FMS-6000
- Dual Collins CDU-6200
- Dual Collins AHS-3000
- Dual Collins CDU-6200 integrated controls
- Dual Collins ADC-3000
- Meggitt MK II secondary flight display
- Dual Collins GPS-4000A sensors
- Dual Collins VIR-432 navigation receivers
- Dual Collins DME-442 Transcievers
- Collins ADF-462

ADDITIONAL EQUIPMENT

- Collins HF-9000 with SELCAL
- Aircell Axxess II Iridium SATCOM
- Honeywell AFIS
- Honeywell Mark V EGPWS
- Collins ALT-4000 radio altimeter
- Collins TWR-850 weather radar
- Collins TTR-4000 (TCAS II) with change 7.0

2002 Hawker 800XP

258588, N799S



INTERIOR

Featuring a forward four place club and an aft three place divan opposite a single forward facing seat



EXTERIOR

Overall Matterhorn White with Blue and Silver accent stripes

2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S



2002 Hawker 800XP

258588 , N799S





North Carolina | Texas | Tennessee | Georgia | Nevada | Arizona | Kansas

Contact: Salesman | email | 704-359-0007